SI72.10-P-0001A	Service Information on adjusting front door lock	19.6.98

MODEL 163

ℹ Repairs concerning complaints about the front door not being able to be opened after unlocking the vehicle, should be addressed in the following manner:

1. Adjust the door lock

2. If attempt to adjust door lock was unsuccessful, replace door lock.

ℹ The majority of door locks being returned under warranty for this complaint have been found to be servicable after adjustment.

1	Adjust front door lock	If adjustment unsuccessful #	AF72.10-P-6003-01A
		Replace front door lock	AR72.10-P-4011GH